

**Parts needed to mount the MICRO-ALU profile**



Mounting bracket (A)



Extrusion (B)



LED strip (C)



Cover (D)



End cap (E)


**Tools needed for mounting:**

- drill
- screwdriver


**WARNING!** All LED strips should be connected to a 12 V or 24 V power supply.

**IMPORTANT:** The mounting instructions present the basic form of assembly. More methods and related accessories can be found at [www.KlusDesign.eu](http://www.KlusDesign.eu)

**1.** Feed the power cable. Attach the mounting bracket (A) to the surface with bolts.



**2.** Install the LED strip (C) in the extrusion (B), insert the cover (D) and the end caps (E).



**3.** Connect power to the LED strip and mount the extrusion (B) in the mounting bracket.

